EXHIBIT H



PACIFIC GAS AND ELECTRIC COMPANY

ELECTRIC INCIDENT REPORT FORM

TO: CALIFORNIA PUBLIC UTILITIES COMMISSION

PG&E Reference Number: EI100124A					
Voice Mail	1/24/2010 8:40:00 PM				
CPUC recipient	Date & Time called in to CPUC				
1-800-235-1076	Curtis Todd Ryan				
Telephone Number	Reported by				
	415-973-2782				
	Telephone Number				
INJURY/FATALITY: An incident which results in a fatality or personal injury to an employee or 3rd party rising to the level of in-patient hospitalization and is attributable or allegedly attributable to utility owned electric facilities. Incidents involving motor vehicles are not reportable unless they result in death or injury attributable or allegedly attributable to electrical contact with the utility owned electric facilities. MEDIA: An incident that is non-storm related, is attributable or allegedly attributable to Pacific Gas and Electric owned electric facilities, and is subject to significant public attention and/or media coverage by three or more qualifying media companies in the Immediate Bay Area. PROPERTY DAMAGE: A single electric incident that is non-storm related where property damage of the utility or a single 3rd party is estimated to exceed \$50,000 and is attributable or allegedly attributable to utility owned electric facilities. (Report required within 60 Days)					
Initial Report Sent to CPUC – Date: 1/25/2010 Fir	al Report Sent to CPUC – Date: 2/18/2010				



PACIFIC GAS AND ELECTRIC COMPANY

ELECTRIC INCIDENT REPORT FORM

PG&E Reference Number: EI100124A

Final

Date and Time of Incident: 1/			1/24/20	10 6:06:0				
Date and Time Incident Determined Reportable:			1/24/2010 8:25:00 PM					
Location of Incident:			Highway Substation					
City:	ty: American Canyon			7		County:	Napa	
Circuit/Facility:		Voltage	:					
Service	Service interrupted (time and date): 1/24/201		10 6:08:0	6:08:00 PM Total Customer		s affected:		15617
Service restored (time and date): 1/24/201		10 9:33:00 PM		Major Customers affected:			TBD	

Description of Incident:

On Sunday January 24, 2010 at 18:07 hours, an outage affecting 15,617 customers occurred at Highway Substation in American Canyon.

The root cause was a switching error that took place at PG&E's Ignacio Substation where 115kV Switch #163 had been left open but had been reported as closed. This set conditions so that when Highway Substation Switch #135 was later opened (normal operating condition), load was dropped, causing a flashover that ultimately de-energized Highway Substation.

PG&E implemented switching procedures and restored electric service to all 15,617 customers at 21:33 hours.

This incident is being reported under the Media criteria: KTVU, KGO, KCBS.

Facility Type: Substation

Injured Party Infomation: No injuries reported.

Property Damage Description: No property damage reported.